

Part - I

**Performa For the Safety School Building**  
**(To be filled by the Head of School/Institute)**

1. Name of School ..... G.H.G. Academy .....
2. Location ..... V.P.O. - Khandoor, Distt. Ludhiana .....
3. Plot Area ..... 29 K, 14 Marla .....
4. Plinth Area ..... 30200 Sq. ft .....
5. Number of Story ..... 04 .....
6. Year of Construction of building ..... 2013 .....
7. Supervision of the qualified Engineer,  
The following details may be given:
- a) Name of Engineer ..... Maneet Goyal .....
- b) Address ..... Jagsaon .....
- c) Set of Structure Drawing used in the  
construction if available ..... All Drawing att. with file .....
- d) Name of the Architect .....
8. Whether the building has been constructed for the purpose of:
- a) School (Yes/No) ..... yes .....
- b) Residential purpose and converted (Yes/No) .....
9. Materials used for Roof:
- a) R.C.C. slabs (Yes/No) ..... yes .....
- b) R.S. Joists and Battens (Yes/No) .....
- c) Wooden Joists Battens (Yes/No) .....
10. Materials used for walls:
- a) Mud mortar (Yes/No) ..... yes .....
- b) Cement Mortar (Yes/No) ..... yes .....
- c) Plaster (i) Lime Mortar (Yes/No) ..... yes .....
- (ii) Cement Mortar (Yes/No) ..... yes .....
11. Flooring:
- a) Conglomerate (Yes/No) ..... yes .....
- b) Terrazzo (Yes/No) .....
- (Yes/No) ..... yes .....

*for  
Principal  
Bagu  
Johal  
66/04/23*

**Principal**  
**G.H.G. Academy**  
**Khandoor (Ldh.)**  
**Affiliated to CBSE**  
**Aff. No. 1630920**





**Part - II**  
**(To be filled by S.D.E. of P.W.D.B&R Department)**  
**G.H.G. Academy, Village Khandoor (Distt. - Ludhiana)**

I have visited the above mentioned school on 5-5-23 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or Caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safety occupied for normal use up to 31-3-24  
(indicate year up to which it can be used).



  
Sub Divisional Engineer  
Constn. Sub Division No.3,  
P.W.D. B & R Br., Ludhiana.  
**Sub Divisional Engineer**  


ਨੰਬਰ:- 43-44

ਮਿਤੀ:- 08/05/23

1. ਪਿੰਸੀਪਲ G.H.G. ACADEMY VILL. KHANDOOR DISTT. LUDHIANA ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਜਾਣਕਾਰੀ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੋ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

  
Sub Divisional Engineer  
Constn. Sub Division No.3,  
P.W.D. B & R Br., Ludhiana.  


G.H.G. ACADEMY  
VILL. KHANDOOR DISTT.  
LUDHIANA  
ALLIED TO C.R.S.E.  
VILL. NO. 1030250